



JAN 05 1995

TERRY E. BRANSTAD, GOVERNOR
January 4, 1995

DEPARTMENT OF NATURAL RESOURCES
LARRY J. WILSON, DIRECTOR

Mr. John Haas, Environmental Project Coordinator
Iowa Department of Transportation
800 Lincoln Way
Ames, IA 50010

SUBJECT: IDOT Garage, 78 South Street, Akron, IA
Tank Registration No. 8609320

LUST No. 8LTZ34

Dear Mr. Haas:

We have completed our review of the analytical results for soil and groundwater samples collected at the above referenced site. The samples were collected to determine the effectiveness of excavation activities to remove the petroleum contamination at the underground storage tank site. The sample results do not exceed the Department's soil or groundwater corrective action levels. No further actions are required at this time. We are assigning a No Action Required classification to the site.

Please be aware the owner is responsible for insuring all wells and borings that accessed groundwater are abandoned and plugged according to Chapter 567-39, Iowa Administrative Code (IAC) once monitoring ceases. DNR Form 542-1226 must be completed and submitted to the department. Contact the designated county agent prior to plugging the abandoned well. Questions pertaining specifically to the procedures to be followed for plugging wells and borings should be directed to the Water Supply Section at 515/281-8599.

A certificate of completion for the investigation may be obtained by submitting a written request and a copy of this letter to me at the address indicated below. The property legal description obtained from the county recorder or abstract must accompany the request if you want to record the certificate with the property deed. As required by 455B.304, subsection 15, Code of Iowa, a certificate may not be issued until at least 90 days have elapsed after the site was assigned the No Action Required classification.

Thank you for your cooperation.

Sincerely,



JAMES R. HUMESTON
ENVIRONMENTAL SPECIALIST
UNDERGROUND STORAGE TANK SECTION

JRH/jrh/8z3301

cc: Field Office 3
GAB Business Services, Inc., POB 3837, Des Moines, IA 50322
W. E. Miner Environmental Consultants, Inc., POB 461, Ames, IA 50010

IOWA DEPARTMENT OF TRANSPORTATION

To Office Environmental Services

Date June 6, 2005

Attention Brad Azeltine

Ref No. 435.1731

From Steven McCauley

Office Materials

Subject Asbestos Inspection

The asbestos inspection requested by Brad Azeltine has been completed. The results are as follows:

COUNTY – Plymouth

PROJECT NO. – None

PARCEL – Akron Maintenance

OWNER – Iowa DOT

ITEM – 21'x16' Office Addition Roof

SAMPLE #1 – Red/brown shingles on main garage office addition, 370 sq. ft.

TEST RESULTS – No asbestos present

SAMPLE #2 – Black roofing felt under shingle on office addition roof, 370 sq. ft.

TEST RESULTS – No asbestos present

SM:kmd

AMES ENVIRONMENTAL, INC.

P.O. BOX 661, 410 MAIN STREET, SLATER, IA 50244, 800-383-3400
 www.amesenvironmental.com, e-mail amesenv@netfins.net

BULK SAMPLE ANALYSIS RESULTS

Client: Iowa Department of Transportation
 Brad Azeltine
 800 Lincoln Way
 Ames, IA 50010

Date of Report: 6/3/2005
 Client No: 466B
 Project Desc.: Submitted by client, Akron Maint.

SAMPLE NUMBER	SAMPLE DESCRIPTION	MATERIALS PRESENT		TOTAL ASBESTOS PERCENTAGE	ANALYSIS DATE	ANALYST
		%	TYPE			
466B68840	Sample #1	45%	Cellulose	0%	6/3/2005	David D. Lester
		5%	Nonfibrous Binders			
		50%	Tar			
466B68841	Sample #2	48%	Cellulose	0%	6/3/2005	David D. Lester
		2%	Nonfibrous Binders			
		50%	Tar			

Analysis by Polarized Light Microscopy using EPA 600/R-93-116 Method for Bulk Sample Analysis. Test results pertain only to the material content of the sample(s) analyzed. PLM has been known to miss asbestos in a small percentage of samples which contain asbestos. Therefore, negative PLM results cannot be guaranteed. Samples reported as <1% or none detected should be tested with TEM. If a floor tile is found to contain no asbestos, the EPA recommends additional testing to prove the lack of asbestos in this material. Percentages of fibrous materials reported are representative of the sample analyzed and not necessarily the percentages in the material as a whole. Member of the American Industrial Hygiene Association (AIHA) Bulk Quality Assurance Program, Laboratory ID: 9821

IOWA DEPARTMENT OF TRANSPORTATION

To Office Environmental Services

Date December 10, 2001

Attention Brad Azeltine

Ref No. 435.1731

From Steven McCauley

Office Materials

Subject Asbestos Inspection

The asbestos inspection requested by Bob Landreth has been completed. The results are as follows:

COUNTY - Plymouth

PROJECT NO. - None

PARCEL - Akron Maintenance Garage

FORMER OWNER - Iowa DOT

ITEM - Akron Maintenance Salt Shed

SAMPLE #1 - Shingles on the roof of the salt shed, 2200 sq. ft.

TEST RESULTS - No asbestos present

SAMPLE #2 - Black paper under the shingles on the salt shed, 2200 sq. ft.

TEST RESULTS - No asbestos present

SM:kmd

DEPARTMENT OF TRANSPORTATION ASBESTOS SURVEY BUILDING SUMMARY

BUILDING NO.: 752A21
 SURVEY DATE: 04/30/92

BUILDING: Garage 5 stall
 LOCATION: Akron at jct 3 & 12

DATE 07/10/92
 PAGE 1

AREA SURVEYED	DESCRIPTION	LOCATION	MATERIAL TYPE	SAMPLE NUMBER	PERCENT ASBEST
---------------	-------------	----------	---------------	---------------	----------------

Bay

4 x 8

ceiling

Accoustical ceiling mat. 2Z043016