




SW Corner
N¹/₂ of 27

NAME Montgomery & State

Section 27 N¹/₂ Township Lehigh County Mower

Contractor _____ Date installed _____

Amount of tile installed 5" _____ 6" _____ 8" _____
10" _____ 12" _____ Larger _____

Regular inspection of the tile system is essential. Prompt repair of any failure will keep the system in working order and maintenance costs low.

IOWA DRAINAGE, INC. SHEFFIELD, IOWA 50475
Jim Blood — Telephone 515-892-4252

AOLSK