

Date: June 28, 2019
Invoice #1052

QTY	DESCRIPTION	UNIT PRICE	AMOUNT
204,835 ft	4 Inch Tile Installed		
8,912 ft	5 Inch Tile Installed		
5,609 ft	6 Inch Tile Installed		
2,320 ft	8 Inch Tile Installed		
520 ft	10 Inch Tile Installed		
64 units	4 Inch Internal Couplers		
186 units	4 Inch End Caps		
9 units	4 Inch Tees		
5 units	5 Inch Internal Couplers		
7 units	5 Inch End Caps		
83 units	5 x 4 Inch Tees		
3 units	6 Inch Internal Couplers		
2 units	6 Inch End Caps		
60 units	6 x 4 Inch Reducing Tees		
3 units	8 Inch Internal Couplers		
2 units	10 Inch Reducing Tees		
2 units	8 Inch SDR Pipe w/ Animal Guard		
2 units	10 Inch SDR Pipe w/ Animal Guard		
6 hours	Labor Time Locating Existing Tile		
6 hours	Excavator Time Locating Existing Tile		
	CBR Drilling to Bore Beneath Railroad Two Times		
	Wet Conditions Required Pull Assistance from Excavator		


PAID
7/25/2019
ck # 1233

Thank you for your business!

17 103N 17W



4 Inch Tile Installed	204834.71 ft
5 Inch Tile	8912.05 ft
6 Inch Tile Installed	5608.58 ft
8 Inch Tile Installed	2320.00 ft
10 Inch Tile Installed	520.00 ft
Existing Tile	1000.00 ft



17 103N 17W
Pipe

EXHIBIT


A

tabbles


580th Ave

Outlet


Existing Tile 196361.74 ft
Randy Johnson 10 Inch Tile Main 2560.45 ft




17 103N 17W
Type



Lateral
Main
Sub-Main




17 103N 17W
Elevation




0 0.12 0.25
miles

17 103N 17VV



Randy Johnson Farm South
Red line is Randy North outlet
TILE

Existing Tile 223195.34 ft
Randy Johnson 10 Inch Main 2559.96 ft



N
W
E
S



Client: Gerlach, Larry
Farm: Red Rock sec 20 NE
Field: Johnson Farm
Name: 10" Main
Date: 10/3/2020

- 10 inch outlet pipe
- 10 inch tile non-perf
- 12 inch road crossing non-perf

